Pendleton Presbyterian Church Broad and South Mechanic Streets Pendleton Anderson County South Carolina HABS No. SC-326

HABS SC, Y-PEND

PHOTOGRAPHS

WRITTEN HISTORICAL AND DESCRIPTIVE DATA

Historic American Buildings Survey National Park Service Department of the Interior Washington, D.C. 20240 Form 10-920 (June 1983)

UNITED STATES DEPARTMENT OF THE INTERIOR NATIONAL PARK SERVICE

HARS St. H-PEND

ARCHITECTURAL DATA FORM

STATE	COUNTY		TOWN OR VICINITY		
South Carolina	Anderson		Pendleton		
HISTORIC NAME OF STRUCTURE (INCLUDE SOURCE FOR NAME) HABS NO.					;
Pendleton Presbyterian Church				SC-32	26
SECONDARY OR COMMON NAMES OF STRUCTURE					
COMPLETE ADORESS (DESCRIBE LOCATION FOR RURAL SITES)					
Broad and South Mechanic Streets					
DATE OF CONSTRUCTION (INCLUOE SOURCE) ARCHITECT(S) (INCLUDE SDURCE)					
1891-1893		C. M. Guest, architect			
SIGNIFICANCE (ARCHITECTURAL AND	Jim Moore, supervisor of construction OUDE ORIGINAL USE DF STRUCTURE)				
Interesting example of late 19th century church design, with use of Gothic Revival motifs.					
STYLE (IF APPROPRIATE)					
Gothic revival elements					
MATERIAL OF CONSTRUCTION (INCLUOE STRUCTURAL SYSTEMS)					
Brick					
SHAPE AND DIMENSIONS OF STRUCTURE (SKETCHED FLODR PLANS DN SEPARATE PAGES ARE ACCEPTABLE)					
Cruciform plan; on the southwest front at the juncture of the horizontal and vertical units are an enclosed entrance porch and a tower with belfry; steep gable roofs except for tower					
EXTERIOR FEATURES OF NOTE which has a pyramidal roof.					
Most door and window openings have gothic arches; windows contain tracery and leaded glass; buttresses with stone copings; exposed rafters at eave line; tower has brick corbeled					
INTERIOR FEATURES OF NOTE (OESCRIBE FLOOR PLANS, IF NOT SKETCHED)					
Auditorium roofed by exposed scissors truss; recessed chancel; wainscoting of vertical					
boards; trim surrounding opening between Sunday School room and auditorium is carved with a grape vine motif in low relief.					
MAJOR ALTERATIONS AND ADDITIONS WITH DATES					
The upper portion of the tower is an addition (the lower section once resembled the still					
extant entrance porch on the other side of the building); a modern addition adjoins the east end of the church.					
PRESENT CONDITION AND USE					
OTHER INFORMATION AS APPROPRIATE					
SOURCES OF INFORMATION (INCLUOING LISTING DN NATIONAL REGISTER, STATE REGISTERS, ETC.)					
Minutes of the Session of the church 1852-1893 and other church records.					
					y
COMPILER, AFFILIATION				DATE	
Druscilla J. Null, HABS			7/9/84		
				7 - 7	